



ECOTECH SERVICES INC... (Analytical Laboratory Division)

Accredited By : NABL, Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO 14001 2004 | OHSAS 18001 : 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M.: 9650160159
E-mail : ecotbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ES/NABL/TR/35

Issued

M/s QRG Health City
P lot No. 01, Sector-16
Faridabad (Haryana)

Test Report No. 5432
Date of Report. 18/10/2017
Work Order No. 00144
Customer Ref... 00144

Description of Sample: One "MCF-Supply" water sample was collected by us on 13/10/2017. The Sample has been tested from 13/10/2017 to 18/10/2017.

TEST REPORT

S.No.	Test Parameters	Unit	Result	Test Method
1.	pH	-	7.30	IS:3025(P-11)
2.	Colour	Hazen	<5	IS:3025(P-4)
3.	Odour	-	Agreeable	IS:3025(P-5)
4.	Total Dissolved Solids	mg / L	3840	IS:3025(P-16)
5.	Chloride as Cl	mg / L	178	IS:3025(P-32)
6.	Sulphate as SO ₄	mg / L	610	IS:3025(P-24)
7.	Calcium as Ca	mg / L	134	IS:3025(P-40)
8.	Magnesium as Mg	mg / L	40	IS:3025(P-46)
9.	Iron as Fe	mg / L	0.05	IS:3025(P-53)
10.	Total Alkalinity	mg / L	390	IS:3025(P-29)
11.	Total Hardness as CaCO ₃	mg / L	844	APHA 22 edit.
12.	Silica as SiO ₂	mg / L	1.4	IS:3025(P-35)

Conditions:-

- ✓ The above mentioned results relates to the tests specified by the customer for the given sample.
- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

---End of report---

(Auth. Signatory)





ECOTECH SERVICES INC... (Analytical Laboratory Division)

Accredited By : NABL, Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO : 14001 : 2004 | OHSAS : 18001 : 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M.: 9650160159
E-mail : ecotbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ES/NABL/TR/35

Issued

M/s QRG Central Hospital & Research Centre
P lot No. 01, Sector-16
Faridabad -Haryana

Test Report No. 5433
Date of Report. 18/10/2017
Work Order No. 00144
Customer Ref... 00144

Description of Sample: Two waste water samples were collected by us on 13/10/2017, "Marked as Inlet of STP & Outlet of STP. The Sample has been tested from 13/10/2017 to 18/10/2017.

TEST REPORT

Sr. No.	Test Parameters	Unit	Results		Discharge Limits as per EPA, Rules 1986 Schedule-VI (See rule 3A)	Specification, standard (method) or technique used.
			Inlet of STP.	Outlet of STP.		
1	pH	-	7.10	7.34	5.5-9.0	IS:3025(P-11)
2	TSS	mg/L	178	08	100	IS:3025 (Part-17)
3	COD	mg/L	402	210	250	IS:3025 (Part-58)
4	BOD at 27 Deg. C for 3 days.	mg/L	54	22	30	IS:3025 (Part-44)
5	Oil & grease	mg/L	1.2	0.1 (ND)	10	IS:3025 (Part-39)

Conditions:-

- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

---End of report---

(Auth. Signature)



ECOTECH SERVICES INC... (Analytical Laboratory Division)

Accredited By : NABL Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO : 14001 : 2004 | OHSAS 18001 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M. : 9650160159
E-mail : ecotbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ES/NABL/TR/35

Issued
M/s QRG Health City.
Plot No. 01 , Sector-16
Faridabad (HRY)
(Haryana)

Test Report No. 5434
Date of Report. 18/10/2017
Work Order No. 00144
Customer Ref... 00144

Description of Sample: One water sample was collected by us on 13/10/2017, Marked as "ETP Outlet". The Sample has been tested from 13/10/2017 to 18/10/2017.


TEST REPORT

Sr. No.	Test Parameters	Unit	Results	Specification, standard (method) or technique used.	Discharge Limits as per EPA-1986 / CPCB / SPCB
1	pH	-	7.64	IS:3025(Part-11)	5.5-9.0
2	TSS	mg/l	30	IS:3025 (Part-17)	100
3	COD	mg/l	204	IS:3025 (Part-58)	250
4	BOD at 27 Deg.C for 3 Days.	mg/l	20	IS:3025 (Part-44)	30
5	Oil & grease	mg/l	0.01(N.D)	IS:3025 (Part-39)	10

Conditions:-

- ✓ The above mentioned results relates to the tests specified by the customer for the given sample.
- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

----End of report----


(Auth. Signatory)



ECOTECH SERVICES INC...

(Analytical Laboratory Division)

Accredited By : NABL, Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
| ISO : 14001 : 2004 | OHSAS : 18001 : 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M. : 9650160159
E-mail : ecofbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ESI/NABL/TR/35

Issued

M/s QRG Central Hospital & Research Centre

Plot No. 01, Sector-16

Faridabad -Haryana

Test Report No. 4825
Date of Report. 26/05/2017
Work Order No. 11229
Customer Ref... 00229

Description of Sample: Two waste water samples were collected by us on 22/05/2017, "Marked as Inlet of STP & Outlet of STP. The Sample has been tested from 22/05/2017 to 25/05/2017.

TEST REPORT


Sr. No.	Test Parameters	Unit	Results		Discharge Limits as per EPA, Rules 1986 Schedule-VI (See rule 3A)	Specification, standard (method) or technique used.
			Inlet of STP.	Outlet of STP.		
1	pH	-	7.07	7.25	5.5-9.0	IS:3025(P-11)
2	TSS	mg/L	169	06	100	IS:3025 (Part-17)
3	COD	mg/L	395	230	250	IS:3025 (Part-58)
4	BOD at 27 Deg. C for 3 days.	mg/L	48	24	30	IS:3025 (Part-44)
5	Oil & grease	mg/L	1.5	0.1 (ND)	10	IS:3025 (Part-39)

Conditions:-

- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is,not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

----End of report----

(Auth Signatory)





ECOTECH SERVICES INC...

(Analytical Laboratory Division)

Accredited By : NABL, Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO : 14001 : 2004 | OHSAS : 18001 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M. : 9650160159
E-mail : ecotbd@yahoo.com, info@ecotechsolutions.in
Website : www.ecotechsolutions.in



NABL
Certificate No TC-5951
Format No. ESI/NABL/TR/35

Issued

M/s QRG Health City.

Plot No. 01 , Sector-16

Faridabad -(HRY)

(Haryana)

Test Report No. **4826**
Date of Report. 26/05/17
Work Order No. **11229**
Customer Ref... 11229

Description of Sample: One water sample was collected by us on 22/05/2017, Marked as 'ETP Outlet'. The Sample has been tested from 22/05/2017 to 26/05/2017.

TEST REPORT

Sr. No.	Test Parameters	Unit	Results	Specification, standard (method) or technique used.	Discharge Limits as per EPA-1986 / CPCB / SPCB
1	pH	-	7.18	IS:3025(Part-11)	5.5-9.0
2	TSS	mg/l	38	IS:3025 (Part-17)	100
3	COD	mg/l	210	IS:3025 (Part-58)	250
4	BOD at 27 Deg.C for 3 Days.	mg/l	22	IS:3025 (Part-44)	30
5	Oil & grease	mg/l	0.01(N.D)	IS:3025 (Part-39)	10

Conditions:-

- ✓ The above mentioned results relates to the tests specified by the customer for the given sample.
- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

----End of report----

(Auth. Signatory)



ECOTECH SERVICES INC...

(Analytical Laboratory Division)

Accredited By : NABL, Deptt. of Science & Technology,
Govt. of India. ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO : 14001 2004 | OHSAS : 18001 - 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M. : 9650160159
E-mail : ecotbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ES/NABL/TR/35

Issued

M/s QRG Health City
Plot No. 01, Sector-16
Faridabad (Haryana)

Test Report No. 4827
Date of Report. 26/05/2017
Work Order No. 11229
Customer Ref.. 11229

Description of Sample: One "Drinking water" sample was collected by us on 22/05/2017, Marked as "R.O. Water". The Sample has been tested from 22/05/2017 to 26/05/2017.

TEST REPORT

S. No	Test Parameters	Unit	Result	Limits as per IS:10500:2012 (Requirement Acceptable Limits)	Limits as per IS:10500:2012 (Permissible limit in the absence of alternative sources)	Test Method
1	Colour	Hazen	Less than 5	5.0max	15max	IS:3025(P-4)
2	Odour	Agreeable	Agreeable	Agreeable	Agreeable	IS:3025(P-5)
3	Taste	Agreeable	Agreeable	Agreeable	Agreeable	IS:3025(P-7&8)
4	Turbidity	NTU	0.2	1.0max.	5.0max.	IS 3025(P-10)
5	Total Dissolved Solids	mg / L	80	500max.	2000max.	IS:3025(P-16)
6	pH value	mg / L	7.14	6.5 to 8.5	No Relaxation	IS:3025(P-11)
7	Nitrate (as NO ₃)	mg / L	1.2	15max.	No Relaxation	IS:3025(P-34)
8	Total Hardness as CaCO ₃	mg / L	10	200max.	600max.	IS:3025(P-21)
9	Chloride as Cl	mg / L	30	250max.	1000max.	IS:3025(P-32)
10	Sulphate as SO ₄	mg / L	<5.0	200max.	400max.	IS:3025(P-24)
11	Boron as B	mg / L	Not Detected	0.5max.	1.0max.	IS:3025(P-57)
12	Fluoride as F	mg / L	Not Detected	1.0max.	1.5max.	IS:3025(P-60)
13	Total Alkalinity as Calcium carbonate	mg / L	28	200max.	600max.	IS:3025(P-23)
14	*Barium as Ba	mg / L	Not Detected	0.7max.	No Relaxation	APHA 22 edit.
15	*Phenolic compounds as C ₆ H ₅ OH.	mg / l.	Not Detected	0.001max.	0.002max.	APHA 22 edit.
16	Iron as Fe	mg / L	Not Detected	0.30max.	No Relaxation	IS:3025(P-53)
17	Manganese as Mn	mg / L	Not Detected	0.1max.	0.3max.	APHA 22 edit.
18	*Copper as Cu	mg / L	Not Detected	0.05max.	1.5max.	IS:3025(P-42)
19	Zinc as Zn	mg / L	Not Detected	5.0max	15max.	IS:3025(P-49)
20	Magnesium as Mg	mg / L	6.4	30max.	100max.	IS:3025(P-46)
21	Calcium as Ca	mg / L	10.8	75max.	200max.	IS:3025(P-40)
22	*Selenium as Se	mg / L	Not Detected	0.01max.	No Relaxation	IS:3025(P-56)
23	*Cadmium as cd	mg / L	Not Detected	0.003max	No relaxation	IS:3025(P-41)
24	*Total Chromium as Cr	mg / L	Not Detected	0.05max	No relaxation	IS:3025(P-52)
25	*Aluminum as Al.	mg / L	Not Detected	0.03max	0.2max	IS:3025(P-55)
26	*Mercury as Hg	mg / L	Not Detected	0.001max	No relaxation	IS:3025(P-48)
27	*Lead as Pb	mg / L	Not Detected	0.01max	No relaxation	IS 3025(P-47)
28	*Total Arsenic as As	mg / L	Not Detected	0.01max	0.05max.	IS:3025(P-37)
29	*Nickel as Ni	mg / L	Not Detected	0.02max	No relaxation	IS:3025(P-54)
30	*Total Coliform Bacteria.	MPN/100ml	Not Detected	No Detectable	No relaxation	IS:1622
31	E.Coli	MPN/100ml	Not Detected	No Detectable	No relaxation	IS:1622

Note: * Not NABL Scope

Remarks: - The above tested parameters are under the specified limits as per IS: 10500:2012 and the water is "FIT" for drinking.

Conditions.

- ✓ The above mentioned results relates to the tests specified by the customer for the given sample.
- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

-----End of Report-----

(Auth. Signatory) AS-ANZ





ECOTECH SERVICES INC... (Analytical Laboratory Division)

A credited By : NABL, Deptt. of Science & Technology,
Govt. of India ISO/IEC : 17025 : 2005 | ISO : 9001 : 2015.
ISO : 4001 : 2004 | OHSAS : 18001 : 2007 Certified.

Plot No. 99, Gali No. 4, Navlu Colony, Railway
Road, Ballabgarh - 121004, FARIDABAD (INDIA)
Tel: +91-129-6590002, 2213006, M.: 9650160159
E-mail : ecotfbd@yahoo.com, info@ecotechservices.in
Website : www.ecotechservices.in



NABL
Certificate No TC-5951
Format No. ES/NABL/TR/35

Issued

M/s QRG Health City
Plot No. 01, Sector-16
Faridabad (Haryana)

Test Report No. 4828
Date of Report. 26/05/2017
Work Order No. 11229
Customer Ref... 11229

Description of Sample: One "MCF-Supply" water sample was collected by us on 22/05/2017. The Sample has been tested from 22/05/2017 to 26/05/2017.

TEST REPORT

S.No.	Test Parameters	Unit	Result	Test Method
1.	pH	-	7.48	IS:3025(P-11)
2.	Colour	Hazen	<5	IS:3025(P-4)
3.	Odour	-	Agreeable	IS:3025(P-5)
4.	Total Dissolved Solids	mg / L	4210	IS:3025(P-16)
5.	Chloride as Cl	mg / L	190	IS:3025(P-32)
6.	Sulphate as SO ₄	mg / L	684	IS:3025(P-24)
7.	Calcium as Ca	mg / L	140	IS:3025(P-40)
8.	Magnesium as Mg	mg / L	44	IS:3025(P-46)
9.	Iron as Fe	mg / L	0.05	IS:3025(P-53)
10.	Total Alkalinity	mg / L	418	IS:3025(P-29)
11.	Total Hardness as CaCO ₃	mg / L	960	APHA 22 edit.
12.	Silica as SiO ₂	mg / L	1.2	IS:3025(P-35)

Conditions:-

- ✓ The above mentioned results relates to the tests specified by the customer for the given sample.
- ✓ The test report shall not be reproduced except in full, without the written approval of the Laboratory.
- ✓ This report is not valid for any publicity/ legal purpose.
- ✓ The test sample will be disposed off after two weeks from the date of issue of report.

---End of report---

(Auth. Signatory)